

# 201302 - Public report

## Unscheduled:

- February 10th: There was an outage on the red link between SUNET and UmU caused by hardware failure
- January 31st: We had a problem with a transmission card restarting. The card was replaced.
- January 28th: Outage detected on 1GE links between SUNET and Onsala rymdobservatorium was caused by a faulty trasmission board that was replaced
- January 25th: A transmission card in the Blue network suffered multiple power cycles and was replaced.

## Scheduled:

- February 24th: Supplier performed a planned maintenance.
- February 14th: A core router was upgraded from a Juniper T640 router to a T1600 router.
- February 13th: A switch was replaced to solve a loss of management problem.
- February 11th: Sitevision was upgraded in order to solve a security bug.
- February 11th: There was a planned work in the west red network.
- February 6th: There was a degraded signal between in SUNET DWDM between the core sites caused by a faulty attenuator. The attenuator was removed.
- February 5th: Software upgrade was performed on SUNET routers.
- February 5th: Software upgrade was performed on SUNET routers.
- February 4th: Software upgrade was performed on SUNET routers.
- February 4th: SUNET's supplier performed a planned cable reconnection maintenance on one of the circuits between Stockholm and Visby.

Scope	Unscheduled	Scheduled	Total
Hardware	1 pcs 00:19	2 pcs 00:30	3 pcs 00:49
Link	3 pcs 00:27	4 pcs 01:29	7 pcs 01:56
None	0 pcs	0 pcs	0 pcs
Routing	0 pcs	0 pcs	0 pcs
Software	0 pcs	4 pcs 05:18	4 pcs 05:18