

201310 - Public report

Unscheduled:

- October 21st: A transponder card was overheated due to fan failure in the equipment which caused traffic to drop. After the card and fans was replaced traffic was restored.
- October 3rd: There was an outage in the South Red network caused by a faulty amplifier card.
- October 4th: Link has been stable since the amplifier was switched again.
- October 1st: A combination of a fiber break and a software bug on a NORDUnet router caused an outage on transit traffic for SUNET and its customers.

Scheduled:

- October 6th: Supplier performed a planned maintenance between Bålsta and Stockholm.
- October 6th: More storage space was added on SUNET Adobe Connect shared storage.
- October 3rd: Fiber maintenance was performed in the North Red network.

Scope	Unscheduled	Scheduled	Total
Hardware	3 pcs 1d 13:51	0 pcs	3 pcs 1d 13:51
Link	0 pcs	2 pcs 4:42	2 pcs 4:42
None	0 pcs	0 pcs	0 pcs
Routing	0 pcs	0 pcs	0 pcs
Software	1pcs 00:34	1 pcs 00:04	2 pcs 00:38