

# 202201 - Public report

## Unscheduled:

- January 20th: The backbone link between Göteborg - Trollhättan had a short flap. RFO unknown.
- January 15th: Problems with FPC-card in router kka8-r1. Solved with replacement of hardware.
- January 12th: RISE CPE alp-c1.sunet.se in Alnarp went down. This was due to a power outage.
- January 10th: Provider performed rerouting of cables due to construction. This affected the link between Göteborg - Stenkullen.
- January 2nd: We had links flapping on FPC0 in oru-r1. The issues was caused by high temperatures. We solved the issue by removing the fan package and cleaning the filters.
- December 31st: We lost connection with the CPE vxj-c1 for RISE Växjö. This was caused by a broken switchport on the access switch belonging to Tele2.

## Scheduled:

- January 17th: Fiber provider performed cable splicing in Kristianstad.
- January 12th: Provider relocated fiber cables due to construction work. This affect the link between Tulegatan - Stockholms Universitet.
- January 12th: Provider performed planed maintenance to change amplifier in site Årnäs. Maintenance affected link between Oslo - Kongsvinger.

| Scope    | Unscheduled    | Scheduled   | Total          |
|----------|----------------|-------------|----------------|
| Hardware | 1 pcs 2d 03:39 | 0 pcs       | 1 pcs 2d 03:39 |
| Link     | 5 pcs 5d 02:23 | 3 pcs 21:24 | 8 pcs 5d 23:47 |
| None     | 0 pcs          | 0 pcs       | 0 pcs          |
| Routing  | 0 pcs          | 0 pcs       | 0 pcs          |
| Software | 0 pcs          | 0 pcs       | 0 pcs          |