202105 - Public report

Unscheduled:

- May 26th: The Link between SUNET and DDB was down after a planned maintenance performed by the circuit provider.
- May 23rd: The CPE vxj-c1 for RISE Växjö were down do a fiber issue that has been fixed by a tele2 subcontractor
- May 18th: The CPE gbg-c4.sunet.se went down to a faulty connection at a station.
- May 17th: The link between bos-r1 bos-c1 went down due to human error at supplier.
- May 7th: The backup layer2 circuit between SUNET core router lin3-r1 and ESS router ess-r2 was down for a short period. No RFO found.
- May 4th: The router slu-r2 rebooted and was unreachable for approximately 10 minutes. RFO was power failure.
- May 3rd: Fiber Interruption that affected the link between OBY2 (Överby) TUG (Stockholm)
- April 27th: The link between Kongsvinger Gaustadallé 23 flapped. RFO unknown
- March 18th: Link down towards Carl Malmsten on Lidingö. Issue solved in SUNETOPS-1413

Scheduled:

- May 27th: FPC2 was replaced in router sva-r1.
- May 26th: The sthb-r2.sunet.se router in Stockholm was upgraded to a new software release.
- May 25th: Supplier performed fiber work in Haparanda. Issues after the maintenance for DDB. We have created SUNETTICKET-7199 to track
 this issue.
- May 25th: The core router in Sundsvall was upgraded to a new software release.
- May 24th: The SUNET core router in Lund was upgraded to a newer software release.
- May 24th: SUNET Core router in Luleå (lla-r1.sunet.se) was upgraded to a new software release.
- May 24th: Supplier performed cabling changes that affected the link between Varla - Holmagärde.
- May 23rd: Subprovider performed fiberwork that affected the link between Kalmar Bergkvara.
- May 20th: Provider performed fibersplicing in multiple locations.
- This affected the links between Rätan Midskog, Midskog Storfinnforsen and Östersund Krångede.
- May 19th: Supplier performed rerouting maintenance that affected the link between Holmagärde Halmstad.
- May 19th: Provider performed fibersplicing in multiple locations.
- That affected the links between Rätan Midskog, Midskog Storfinnforsen and Östersund Krångede.
- May 18th: Supplier performed fiber maintenance in their network.
 - This affected the link between Göteborg and Onsala.
- May 18th: SUNET performed software upgrade on the core router in Umeå.
- May 17th: SUNET performed software upgrade on our core router in Luleå.
- May 17th: Fiber provider performed measurements after fiber replacement.
- May 11th: Provider performed cable maintenance between Kalmar and Karlskrona.
- May 8th: Sub-provider rebuilt power lines between Lindbacka and Himmeta in Sweden.
- May 6th: Planned maintenance to replace of optics in bos-c2. New QSFP did not work and will be sent back to SUNET for investigation.
- May 5th: The SUNET core router in Stockholm (tug-r1) was upgraded to a new software release.
- May 5th: Supplier performed rerouting maintenance that affected the link between Göteborg Varla.
- May 3rd: Supplier performed an emergency network maintenance on the link between Holmagärde and Falkenberg.

Scope	Unscheduled	Scheduled	Total
Hardware	1 pcs 00:10	3 pcs 01:14	4 pcs 01:24
Link	6 pcs 4d 03:09	13 pcs 2d 01:15	19 pcs 6d 04:24
None	2 pcs 45d 23:38	3 pcs 01:37	5 pcs 46d 01:15
Routing	0 pcs	1 pcs 00:39	1 pcs 00:39
Software	0 pcs	1 pcs 00:39	1 pcs 00:39