

# 201411 - Public report

## Unscheduled:

- November 25th: A faulty card caused node to power restart. Faulty card has been replaced.
- November 23: Red and Green link to CTH was down due a planned work on Green link and a fault on the Red link.
- November 7th: An equipment in Listlena was down due to power problems on site. This has now been resolved.
- November 7th: There was an outage on the south green network due to an unannounced planned maintenance by carrier.
- November 3rd: There was a power restart on the main card on the node SR\_421\_K\_OH. Solved by replacing the card.
- November 2nd: SH link was down due to power problems at customers site.
- November 1st: The redundancy link between Inu-br1 and Inu-br2 was flapping. No further flaps detected.
- November 1st: md.nordu.net was not working. Solved by reboot.
- October 30th: There was an outage on the south green network due to an unannounced planned maintenance by carrier.
- November 11th: We had a degraded signal on the circuit to Luleå. After being moved to a new fiber pair all levels are ok.

## Scheduled:

- November 19th: Carrier performed a planned maintenance to resplice fiber on the circuit between Karlstad and Hanebol.
- November 16th: Subcontractor performed a resplice of dark-fiber between Norrköping and Linköping.

Scope	Unscheduled	Scheduled	Total
Hardware	1 pcs 00:05	0 pcs	1 pcs 00:05
Link	4 pcs 16:58	2 pcs 04:02	6 pcs 21:00
None	5 pcs 10:01	0 pcs	5 pcs 10:01
Routing	0 pcs	0 pcs	0 pcs
Software	0 pcs	0 pcs	0 pcs