

202107 - Public report

Unscheduled:

- July 15th: There was a fiber break on the stretch between Abisko and Rensjön. Fiber was fixed and services restored.
- July 9th: The fpc4 on lla-r2 restarted multiple times and caused service interruption.
Solved with replacement.
- July 8th: The link between Järpen and Kopparå went down due to unannounced fiber maintenance carried out by subprovider.
- July 6th: The link between kau-r2 and trh-r1 was down due to a faulty fiber. Fiber has been repaired and service restored.

Scheduled:

- July 29th: The following routers were upgraded to a new software release:
cth-r1, ess-r1 and su-r1.
- July 29th: A faulty card was replaced on the SUNET core router in Sundsvall.
- July 28th: Provider performed fiber maintenance affecting the link between Kiruna - Kalix.
- July 27th: The following routers were upgraded to a new software release:
cth-r2, ess-r2 and su-r2
- July 8th: Supplier performed mandatory maintenance in Midskog which affected the fiber stretch Midskog - Östersund.

Scope	Unscheduled	Scheduled	Total
Hardware	1 pcs 02:12	0 pcs	1 pcs 02:12
Link	3 pcs 2d 19:03	2 pcs 08:27	5 pcs 3d 03:30
None	0 pcs	1 pcs 00:07	1 pcs 00:07
Routing	0 pcs	0 pcs	0 pcs
Software	0 pcs	2 pcs 02:17	2 pcs 02:17